


# Data sheet

## OpDAT strain relief for M20


Page 1/15

P/N  
150240Z20Z-E  
EAN 4251394679761  
2025/07/11  
Version: B

### Illustrations



Dimensional drawing



See enlarged drawings at the end of document

### Product specification

- Strain relief for M20 screw connection



**Data sheet**  
**OpDAT strain relief for M20**

Page 2/15

**P/N**  
**150240Z20Z-E**  
**EAN 4251394679761**  
 2025/07/11  
 Version: B

**Technical Data**

**General Data**

Ingress measurement according to MICE	I1
Climatic measurement according to MICE	C1
Electromagnetic measurement according to MICE	E3
Design	strain relief
Mounting style	Accessories
Color	gray
Dimensions	
Dimension (L x W x H)	38.75 mm x 26 mm x 30.5 mm
Dimension (L x W x H)	1.526 in. x 1.024 in. x 1.201 in.

**Materials and material properties**

Halogen free	yes
RoHS	compliant

**Classifications**

ETIM 8.0	EC002939
ETIM 9.0	EC002939
ETIM 10.0	EC002939

**Packing details**

Type of packaging	1 pc(s) / plastic bag
-------------------	-----------------------

**Application note**

This product is a standard product of METZ CONNECT. METZ CONNECT is not aware of the specific intended use of the goods by the Customer or any customers of the Customer. The Customer guarantees that it has fully and sufficiently tested the use of the goods and any product modifications, product changes or product enhancements with regard to the specific intended use in accordance with the state of the art or in any other way. At METZ CONNECT's request, the Customer shall submit and make available meaningful evidence (e.g. test and laboratory protocols, certifications, etc.).

# OpDAT strain relief for M20

P/N

150240Z20Z-E

EAN 4251394679761

2025/07/11

Version: B

## Accessories from

P/N	Designation
1504500000-E	OpDAT fix <sup>2</sup> patch panel connect gray
1504505906-C	OpDAT fix <sup>2</sup> patch panel VIK 6xE2000-S APC OS2 black
1504505906-F	OpDAT fix <sup>2</sup> patch panel VIK 6xE2000-S APC OS2 gray
1504505912-C	OpDAT fix <sup>2</sup> patch panel VIK 12xE2000-S APC OS2 black
1504505912-F	OpDAT fix <sup>2</sup> patch panel VIK 12xE2000-S APC OS2 gray
1504505924-B	OpDAT fix <sup>2</sup> patch panel VIK 24xE2000-S APC OS2 black
1504505924-E	OpDAT fix <sup>2</sup> patch panel VIK 24xE2000-S APC OS2 gray
1504507406-C	OpDAT fix <sup>2</sup> patch panel VIK 6xLC-D OS2 black
1504507406-F	OpDAT fix <sup>2</sup> patch panel VIK 6xLC-D OS2 gray
1504507412-C	OpDAT fix <sup>2</sup> patch panel VIK 12xLC-D OS2 black
1504507412-F	OpDAT fix <sup>2</sup> patch panel VIK 12xLC-D OS2 gray
1504507424-B	OpDAT fix <sup>2</sup> patch panel VIK 24xLC-D OS2 black
1504507424-E	OpDAT fix <sup>2</sup> patch panel VIK 24xLC-D OS2 gray
1504507506-C	OpDAT fix <sup>2</sup> patch panel VIK 6xLC-D OM4 black
1504507506-F	OpDAT fix <sup>2</sup> patch panel VIK 6xLC-D OM4 gray
1504507512-C	OpDAT fix <sup>2</sup> patch panel VIK 12xLC-D OM4 black
1504507512-F	OpDAT fix <sup>2</sup> patch panel VIK 12xLC-D OM4 gray
1504507524-B	OpDAT fix <sup>2</sup> patch panel VIK 24xLC-D OM4 black
1504507524-E	OpDAT fix <sup>2</sup> patch panel VIK 24xLC-D OM4 gray
1504507606-C	OpDAT fix <sup>2</sup> patch panel VIK 6xLC-D APC OS2 black
1504507606-F	OpDAT fix <sup>2</sup> patch panel VIK 6xLC-D APC OS2 gray

# OpDAT strain relief for M20

P/N

150240Z20Z-E

EAN 4251394679761

2025/07/11

Version: B

## Accessories from

1504507612-C	OpDAT fix <sup>2</sup> patch panel VIK 12xLC-D APC OS2 black
1504507612-F	OpDAT fix <sup>2</sup> patch panel VIK 12xLC-D APC OS2 gray
1504507624-B	OpDAT fix <sup>2</sup> patch panel VIK 24xLC-D APC OS2 black
1504507624-E	OpDAT fix <sup>2</sup> patch panel VIK 24xLC-D APC OS2 gray
1504507706-C	OpDAT fix <sup>2</sup> patch panel VIK 6xLC-D OM3 black
1504507706-F	OpDAT fix <sup>2</sup> patch panel VIK 6xLC-D OM3 gray
1504507712-C	OpDAT fix <sup>2</sup> patch panel VIK 12xLC-D OM3 black
1504507712-F	OpDAT fix <sup>2</sup> patch panel VIK 12xLC-D OM3 gray
1504507724-B	OpDAT fix <sup>2</sup> patch panel VIK 24xLC-D OM3 black
1504507724-E	OpDAT fix <sup>2</sup> patch panel VIK 24xLC-D OM3 gray
1504507M06-F	OpDAT fix <sup>2</sup> patch panel VIK 6xLC-D OM5 gray
1504507M12-F	OpDAT fix <sup>2</sup> patch panel VIK 12xLC-D OM5 gray
1504507M24-E	OpDAT fix <sup>2</sup> patch panel VIK 24xLC-D OM5 gray
150450BA06-F	OpDAT fix <sup>2</sup> patch panel VIK 6xSC-D OM3 gray
150450BA12-F	OpDAT fix <sup>2</sup> patch panel VIK 12xSC-D OM3 gray
150450BA24-E	OpDAT fix <sup>2</sup> patch panel VIK 24xSC-D OM3 gray
150450BB06-F	OpDAT fix <sup>2</sup> patch panel VIK 6xSC-D OM4 gray
150450BB12-F	OpDAT fix <sup>2</sup> patch panel VIK 12xSC-D OM4 gray
150450BB24-E	OpDAT fix <sup>2</sup> patch panel VIK 24xSC-D OM4 gray
150450BM06-F	OpDAT fix <sup>2</sup> patch panel VIK 6xSC-D OM5 gray
150450BM12-F	OpDAT fix <sup>2</sup> patch panel VIK 12xSC-D OM5 gray
150450BM24-E	OpDAT fix <sup>2</sup> patch panel VIK 24xSC-D OM5 gray



# OpDAT strain relief for M20

P/N

150240Z20Z-E

EAN 4251394679761

2025/07/11

Version: B

## Accessories from

150450D106-F	OpDAT fix <sup>2</sup> patch panel VIK 6xST-D gray
150450D112-F	OpDAT fix <sup>2</sup> patch panel VIK 12xST-D gray
150450D124-E	OpDAT fix <sup>2</sup> patch panel VIK 24xST-D gray
150450E206-C	OpDAT fix <sup>2</sup> patch panel VIK 6xSC-D OS2 black
150450E206-F	OpDAT fix <sup>2</sup> patch panel VIK 6xSC-D OS2 gray
150450E212-C	OpDAT fix <sup>2</sup> patch panel VIK 12xSC-D OS2 black
150450E212-F	OpDAT fix <sup>2</sup> patch panel VIK 12xSC-D OS2 gray
150450E224-B	OpDAT fix <sup>2</sup> patch panel VIK 24xSC-D OS2 black
150450E224-E	OpDAT fix <sup>2</sup> patch panel VIK 24xSC-D OS2 gray
150450F206-C	OpDAT fix <sup>2</sup> patch panel VIK 6xSC-D APC OS2 black
150450F206-F	OpDAT fix <sup>2</sup> patch panel VIK 6xSC-D APC OS2 gray
150450F212-C	OpDAT fix <sup>2</sup> patch panel VIK 12xSC-D APC OS2 black
150450F212-F	OpDAT fix <sup>2</sup> patch panel VIK 12xSC-D APC OS2 gray
150450F224-B	OpDAT fix <sup>2</sup> patch panel VIK 24xSC-D APC OS2 black
150450F224-E	OpDAT fix <sup>2</sup> patch panel VIK 24xSC-D APC OS2 gray
1504557706-C	OpDAT fix <sup>2</sup> patch panel splice 6xLC-D OM3 black
1504557706-F	OpDAT fix <sup>2</sup> patch panel splice 6xLC-D OM3 gray
1504557712-C	OpDAT fix <sup>2</sup> patch panel splice 12xLC-D OM3 black
1504557712-F	OpDAT fix <sup>2</sup> patch panel splice 12xLC-D OM3 gray
1504557724-B	OpDAT fix <sup>2</sup> patch panel splice 24xLC-D OM3 black
1504557724-E	OpDAT fix <sup>2</sup> patch panel splice 24xLC-D OM3 gray
150455BA06-F	OpDAT fix <sup>2</sup> patch panel splice 6xSC-D OM3 gray

# OpDAT strain relief for M20

P/N

150240Z20Z-E

EAN 4251394679761

2025/07/11

Version: B

## Accessories from

150455BA12-F	OpDAT fix <sup>2</sup> patch panel splice 12xSC-D OM3 gray
150455BA24-E	OpDAT fix <sup>2</sup> patch panel splice 24xSC-D OM3 gray
150455D106-F	OpDAT fix <sup>2</sup> patch panel splice 6xST-D OM3 gray
150455D112-F	OpDAT fix <sup>2</sup> patch panel splice 12xST-D OM3 gray
150455D124-E	OpDAT fix <sup>2</sup> patch panel splice 24xST-D OM3 gray
1504577506-C	OpDAT fix <sup>2</sup> patch panel splice 6xLC-D OM4 black
1504577506-F	OpDAT fix <sup>2</sup> patch panel splice 6xLC-D OM4 gray
1504577512-C	OpDAT fix <sup>2</sup> patch panel splice 12xLC-D OM4 black
1504577512-F	OpDAT fix <sup>2</sup> patch panel splice 12xLC-D OM4 gray
1504577524-B	OpDAT fix <sup>2</sup> patch panel splice 24xLC-D OM4 black
1504577524-E	OpDAT fix <sup>2</sup> patch panel splice 24xLC-D OM4 gray
150457BB06-F	OpDAT fix <sup>2</sup> patch panel splice 6xSC-D OM4 gray
150457BB12-F	OpDAT fix <sup>2</sup> patch panel splice 12xSC-D OM4 gray
150457BB24-E	OpDAT fix <sup>2</sup> patch panel splice 24xSC-D OM4 gray
150457D106-F	OpDAT fix <sup>2</sup> patch panel splice 6xST-D OM4 gray
150457D112-F	OpDAT fix <sup>2</sup> patch panel splice 12xST-D OM4 gray
150457D124-E	OpDAT fix <sup>2</sup> patch panel splice 24xST-D OM4 gray
1504587M06-F	OpDAT fix <sup>2</sup> patch panel splice 6xLC-D OM5 gray
1504587M12-F	OpDAT fix <sup>2</sup> patch panel splice 12xLC-D OM5 gray
1504587M24-E	OpDAT fix <sup>2</sup> patch panel splice 24xLC-D OM5 gray
150458BM06-F	OpDAT fix <sup>2</sup> patch panel splice 6xSC-D OM5 gray
150458BM12-F	OpDAT fix <sup>2</sup> patch panel splice 12xSC-D OM5 gray

**OpDAT strain relief for M20**

P/N

150240Z20Z-E

EAN 4251394679761

2025/07/11

Version: B

**Accessories from**

150458BM24-E	OpDAT fix <sup>2</sup> patch panel splice 24xSC-D OM5 gray
1504595906-C	OpDAT fix <sup>2</sup> patch panel splice 6xE2000-S APC OS2 black
1504595906-F	OpDAT fix <sup>2</sup> patch panel splice 6xE2000-S APC OS2 gray
1504595912-C	OpDAT fix <sup>2</sup> patch panel splice 12xE2000-S APC OS2 black
1504595912-F	OpDAT fix <sup>2</sup> patch panel splice 12xE2000-S APC OS2 gray
1504595924-B	OpDAT fix <sup>2</sup> patch panel splice 24xE2000-S APC OS2 black
1504595924-E	OpDAT fix <sup>2</sup> patch panel splice 24xE2000-S APC OS2 gray
1504597406-C	OpDAT fix <sup>2</sup> patch panel splice 6xLC-D OS2 black
1504597406-F	OpDAT fix <sup>2</sup> patch panel splice 6xLC-D OS2 gray
1504597412-C	OpDAT fix <sup>2</sup> patch panel splice 12xLC-D OS2 black
1504597412-F	OpDAT fix <sup>2</sup> patch panel splice 12xLC-D OS2 gray
1504597424-B	OpDAT fix <sup>2</sup> patch panel splice 24xLC-D OS2 black
1504597424-E	OpDAT fix <sup>2</sup> patch panel splice 24xLC-D OS2 gray
1504597606-C	OpDAT fix <sup>2</sup> patch panel splice 6xLC-D APC OS2 black
1504597606-F	OpDAT fix <sup>2</sup> patch panel splice 6xLC-D APC OS2 gray
1504597612-C	OpDAT fix <sup>2</sup> patch panel splice 12xLC-D APC OS2 black
1504597612-F	OpDAT fix <sup>2</sup> patch panel splice 12xLC-D APC OS2 gray
1504597624-B	OpDAT fix <sup>2</sup> patch panel splice 24xLC-D APC OS2 black
1504597624-E	OpDAT fix <sup>2</sup> patch panel splice 24xLC-D APC OS2 gray
150459D106-F	OpDAT fix <sup>2</sup> patch panel splice 6xST-D OS2 gray
150459D112-F	OpDAT fix <sup>2</sup> patch panel splice 12xST-D OS2 gray
150459D124-E	OpDAT fix <sup>2</sup> patch panel splice 24xST-D OS2 gray



# OpDAT strain relief for M20

P/N

150240Z20Z-E

EAN 4251394679761

2025/07/11

Version: B

## Accessories from

150459E206-C	OpDAT fix <sup>2</sup> patch panel splice 6xSC-D OS2 black
150459E206-F	OpDAT fix <sup>2</sup> patch panel splice 6xSC-D OS2 gray
150459E212-C	OpDAT fix <sup>2</sup> patch panel splice 12xSC-D OS2 black
150459E212-F	OpDAT fix <sup>2</sup> patch panel splice 12xSC-D OS2 gray
150459E224-B	OpDAT fix <sup>2</sup> patch panel splice 24xSC-D OS2 black
150459E224-E	OpDAT fix <sup>2</sup> patch panel splice 24xSC-D OS2 gray
150459F206-C	OpDAT fix <sup>2</sup> patch panel splice 6xSC-D APC OS2 black
150459F206-F	OpDAT fix <sup>2</sup> patch panel splice 6xSC-D APC OS2 gray
150459F212-C	OpDAT fix <sup>2</sup> patch panel splice 12xSC-D APC OS2 black
150459F212-F	OpDAT fix <sup>2</sup> patch panel splice 12xSC-D APC OS2 gray
150459F224-B	OpDAT fix <sup>2</sup> patch panel splice 24xSC-D APC OS2 black
150459F224-E	OpDAT fix <sup>2</sup> patch panel splice 24xSC-D APC OS2 gray
15045FJJ12-F	OpDAT fix <sup>2</sup> patch panel VIK 12xLC-D OS2/OM4 gray
1504601C00-E	OpDAT slide <sup>2</sup> patch panel splice unequipped gray
1504605906-C	OpDAT slide <sup>2</sup> patch panel VIK 6xE2000-S APC OS2 black
1504605906-F	OpDAT slide <sup>2</sup> patch panel VIK 6xE2000-S APC OS2 gray
1504605912-C	OpDAT slide <sup>2</sup> patch panel VIK 12xE2000-S APC OS2 black
1504605912-F	OpDAT slide <sup>2</sup> patch panel VIK 12xE2000-S APC OS2 gray
1504605924-B	OpDAT slide <sup>2</sup> patch panel VIK 24xE2000-S APC OS2 black
1504605924-E	OpDAT slide <sup>2</sup> patch panel VIK 24xE2000-S APC OS2 gray
1504607406-C	OpDAT slide <sup>2</sup> patch panel VIK 6xLC-D OS2 black
1504607406-F	OpDAT slide <sup>2</sup> patch panel VIK 6xLC-D OS2 gray

**OpDAT strain relief for M20**

P/N

**150240Z20Z-E****EAN 4251394679761**

2025/07/11

Version: B

**Accessories from**

1504607412-C	OpDAT slide <sup>2</sup> patch panel VIK 12xLC-D OS2 black
1504607412-F	OpDAT slide <sup>2</sup> patch panel VIK 12xLC-D OS2 gray
1504607424-B	OpDAT slide <sup>2</sup> patch panel VIK 24xLC-D OS2 black
1504607424-E	OpDAT slide <sup>2</sup> patch panel VIK 24xLC-D OS2 gray
1504607506-C	OpDAT slide <sup>2</sup> patch panel VIK 6xLC-D OM4 black
1504607506-F	OpDAT slide <sup>2</sup> patch panel VIK 6xLC-D OM4 gray
1504607512-C	OpDAT slide <sup>2</sup> patch panel VIK 12xLC-D OM4 black
1504607512-F	OpDAT slide <sup>2</sup> patch panel VIK 12xLC-D OM4 gray
1504607524-B	OpDAT slide <sup>2</sup> patch panel VIK 24xLC-D OM4 black
1504607524-E	OpDAT slide <sup>2</sup> patch panel VIK 24xLC-D OM4 gray
1504607606-C	OpDAT slide <sup>2</sup> patch panel VIK 6xLC-D APC OS2 black
1504607606-F	OpDAT slide <sup>2</sup> patch panel VIK 6xLC-D APC OS2 gray
1504607612-C	OpDAT slide <sup>2</sup> patch panel VIK 12xLC-D APC OS2 black
1504607612-F	OpDAT slide <sup>2</sup> patch panel VIK 12xLC-D APC OS2 gray
1504607624-B	OpDAT slide <sup>2</sup> patch panel VIK 24xLC-D APC OS2 black
1504607624-E	OpDAT slide <sup>2</sup> patch panel VIK 24xLC-D APC OS2 gray
1504607706-C	OpDAT slide <sup>2</sup> patch panel VIK 6xLC-D OM3 black
1504607706-F	OpDAT slide <sup>2</sup> patch panel VIK 6xLC-D OM3 gray
1504607712-C	OpDAT slide <sup>2</sup> patch panel VIK 12xLC-D OM3 black
1504607712-F	OpDAT slide <sup>2</sup> patch panel VIK 12xLC-D OM3 gray
1504607724-B	OpDAT slide <sup>2</sup> patch panel VIK 24xLC-D OM3 black
1504607724-E	OpDAT slide <sup>2</sup> patch panel VIK 24xLC-D OM3 gray



## OpDAT strain relief for M20

P/N

150240Z20Z-E

EAN 4251394679761

2025/07/11

Version: B

### Accessories from

1504607M06-F	OpDAT slide <sup>2</sup> patch panel VIK 6xLC-D OM5 gray
1504607M12-F	OpDAT slide <sup>2</sup> patch panel VIK 12xLC-D OM5 gray
1504607M24-E	OpDAT slide <sup>2</sup> patch panel VIK 24xLC-D OM5 gray
150460BA00-E	OpDAT slide <sup>2</sup> patch panel unequipped gray
150460BA06-F	OpDAT slide <sup>2</sup> patch panel VIK 6xSC-D OM3 gray
150460BA12-F	OpDAT slide <sup>2</sup> patch panel VIK 12xSC-D OM3 gray
150460BA24-E	OpDAT slide <sup>2</sup> patch panel VIK 24xSC-D OM3 gray
150460BB06-F	OpDAT slide <sup>2</sup> patch panel VIK 6xSC-D OM4 gray
150460BB12-F	OpDAT slide <sup>2</sup> patch panel VIK 12xSC-D OM4 gray
150460BB24-E	OpDAT slide <sup>2</sup> patch panel VIK 24xSC-D OM4 gray
150460BM24-E	OpDAT slide <sup>2</sup> patch panel VIK 24xSC-D OM5 gray
150460D124-E	OpDAT slide <sup>2</sup> patch panel VIK 24xST-D gray
150460E206-C	OpDAT slide <sup>2</sup> patch panel VIK 6xSC-D OS2 black
150460E206-F	OpDAT slide <sup>2</sup> patch panel VIK 6xSC-D OS2 gray
150460E212-C	OpDAT slide <sup>2</sup> patch panel VIK 12xSC-D OS2 black
150460E212-F	OpDAT slide <sup>2</sup> patch panel VIK 12xSC-D OS2 gray
150460E224-B	OpDAT slide <sup>2</sup> patch panel VIK 24xSC-D OS2 black
150460E224-E	OpDAT slide <sup>2</sup> patch panel VIK 24xSC-D OS2 gray
150460F206-C	OpDAT slide <sup>2</sup> patch panel VIK 6xSC-D APC OS2 black
150460F206-F	OpDAT slide <sup>2</sup> patch panel VIK 6xSC-D APC OS2 gray
150460F212-C	OpDAT slide <sup>2</sup> patch panel VIK 12xSC-D APC OS2 black
150460F212-F	OpDAT slide <sup>2</sup> patch panel VIK 12xSC-D APC OS2 gray

## OpDAT strain relief for M20

P/N

150240Z20Z-E

EAN 4251394679761

2025/07/11

Version: B

### Accessories from

150460F224-B	OpDAT slide <sup>2</sup> patch panel VIK 24xSC-D APC OS2 black
150460F224-E	OpDAT slide <sup>2</sup> patch panel VIK 24xSC-D APC OS2 gray
1504657706-C	OpDAT slide <sup>2</sup> patch panel splice 6xLC-D OM3 black
1504657706-F	OpDAT slide <sup>2</sup> patch panel splice 6xLC-D OM3 gray
1504657712-C	OpDAT slide <sup>2</sup> patch panel splice 12xLC-D OM3 black
1504657712-F	OpDAT slide <sup>2</sup> patch panel splice 12xLC-D OM3 gray
1504657724-B	OpDAT slide <sup>2</sup> patch panel splice 24xLC-D OM3 black
1504657724-E	OpDAT slide <sup>2</sup> patch panel splice 24xLC-D OM3 gray
150465BA06-F	OpDAT slide <sup>2</sup> patch panel splice 6xSC-D OM3 gray
150465BA12-F	OpDAT slide <sup>2</sup> patch panel splice 12xSC-D OM3 gray
150465BA24-E	OpDAT slide <sup>2</sup> patch panel splice 24xSC-D OM3 gray
150465D106-F	OpDAT slide <sup>2</sup> patch panel splice 6xST-D OM3 gray
150465D112-F	OpDAT slide <sup>2</sup> patch panel splice 12xST-D OM3 gray
150465D124-E	OpDAT slide <sup>2</sup> patch panel splice 24xST-D OM3 gray
1504677506-C	OpDAT slide <sup>2</sup> patch panel splice 6xLC-D OM4 black
1504677506-E	
1504677506-F	OpDAT slide <sup>2</sup> patch panel splice 6xLC-D OM4 gray
1504677512-C	OpDAT slide <sup>2</sup> patch panel splice 12xLC-D OM4 black
1504677512-F	OpDAT slide <sup>2</sup> patch panel splice 12xLC-D OM4 gray
1504677524-B	OpDAT slide <sup>2</sup> patch panel splice 24xLC-D OM4 black
1504677524-E	OpDAT slide <sup>2</sup> patch panel splice 24xLC-D OM4 gray
150467BB06-F	OpDAT slide <sup>2</sup> patch panel splice 6xSC-D OM4 gray

# OpDAT strain relief for M20

P/N

150240Z20Z-E

EAN 4251394679761

2025/07/11

Version: B

## Accessories from

150467BB12-F	OpDAT slide <sup>2</sup> patch panel splice 12xSC-D OM4 gray
150467BB24-E	OpDAT slide <sup>2</sup> patch panel splice 24xSC-D OM4 gray
150467D106-F	OpDAT slide <sup>2</sup> patch panel splice 6xST-D OM4 gray
150467D112-F	OpDAT slide <sup>2</sup> patch panel splice 12xST-D OM4 gray
150467D124-E	OpDAT slide <sup>2</sup> patch panel splice 24xST-D OM4 gray
1504687M06-F	OpDAT slide <sup>2</sup> patch panel splice 6xLC-D OM5 gray
1504687M12-F	OpDAT slide <sup>2</sup> patch panel splice 12xLC-D OM5 gray
1504687M24-E	OpDAT slide <sup>2</sup> patch panel splice 24xLC-D OM5 gray
150468BM06-F	OpDAT slide <sup>2</sup> patch panel splice 6xSC-D OM5 gray
150468BM12-F	OpDAT slide <sup>2</sup> patch panel splice 12xSC-D OM5 gray
150468BM24-E	OpDAT slide <sup>2</sup> patch panel splice 24xSC-D OM5 gray
1504695906-C	OpDAT slide <sup>2</sup> patch panel splice 6xE2000-S APC OS2 black
1504695906-F	OpDAT slide <sup>2</sup> patch panel splice 6xE2000-S APC OS2 gray
1504695912-C	OpDAT slide <sup>2</sup> patch panel splice 12xE2000-S APC OS2 black
1504695912-F	OpDAT slide <sup>2</sup> patch panel splice 12xE2000-S APC OS2 gray
1504695924-B	OpDAT slide <sup>2</sup> patch panel splice 24xE2000-S APC OS2 black
1504695924-E	OpDAT slide <sup>2</sup> patch panel splice 24xE2000-S APC OS2 gray
1504697406-C	OpDAT slide <sup>2</sup> patch panel splice 6xLC-D OS2 black
1504697406-F	OpDAT slide <sup>2</sup> patch panel splice 6xLC-D OS2 gray
1504697412-C	OpDAT slide <sup>2</sup> patch panel splice 12xLC-D OS2 black
1504697412-F	OpDAT slide <sup>2</sup> patch panel splice 12xLC-D OS2 gray
1504697424-B	OpDAT slide <sup>2</sup> patch panel splice 24xLC-D OS2 black

# OpDAT strain relief for M20

P/N

150240Z20Z-E

EAN 4251394679761

2025/07/11

Version: B

## Accessories from

1504697424-E	OpDAT slide <sup>2</sup> patch panel splice 24xLC-D OS2 gray
1504697606-C	OpDAT slide <sup>2</sup> patch panel splice 6xLC-D APC OS2 black
1504697606-F	OpDAT slide <sup>2</sup> patch panel splice 6xLC-D APC OS2 gray
1504697612-C	OpDAT slide <sup>2</sup> patch panel splice 12xLC-D APC OS2 black
1504697612-F	OpDAT slide <sup>2</sup> patch panel splice 12xLC-D APC OS2 gray
1504697624-B	OpDAT slide <sup>2</sup> patch panel splice 24xLC-D APC OS2 black
1504697624-E	OpDAT slide <sup>2</sup> patch panel splice 24xLC-D APC OS2 gray
150469D106-F	OpDAT slide <sup>2</sup> patch panel splice 6xST-D OS2 gray
150469D112-F	OpDAT slide <sup>2</sup> patch panel splice 12xST-D OS2 gray
150469D124-E	OpDAT slide <sup>2</sup> patch panel splice 24xST-D OS2 gray
150469E206-C	OpDAT slide <sup>2</sup> patch panel splice 6xSC-D OS2 black
150469E206-F	OpDAT slide <sup>2</sup> patch panel splice 6xSC-D OS2 gray
150469E212-C	OpDAT slide <sup>2</sup> patch panel splice 12xSC-D OS2 black
150469E212-F	OpDAT slide <sup>2</sup> patch panel splice 12xSC-D OS2 gray
150469E224-B	OpDAT slide <sup>2</sup> patch panel splice 24xSC-D OS2 black
150469E224-E	OpDAT slide <sup>2</sup> patch panel splice 24xSC-D OS2 gray
150469F206-C	OpDAT slide <sup>2</sup> patch panel splice 6xSC-D APC OS2 black
150469F206-F	OpDAT slide <sup>2</sup> patch panel splice 6xSC-D APC OS2 gray
150469F212-C	OpDAT slide <sup>2</sup> patch panel splice 12xSC-D APC OS2 black
150469F212-F	OpDAT slide <sup>2</sup> patch panel splice 12xSC-D APC OS2 gray
150469F224-B	OpDAT slide <sup>2</sup> patch panel splice 24xSC-D APC OS2 black
150469F224-E	OpDAT slide <sup>2</sup> patch panel splice 24xSC-D APC OS2 gray

# OpDAT strain relief for M20

P/N

150240Z20Z-E

EAN 4251394679761

2025/07/11

Version: B

## Accessories from

1504805948-E	OpDAT fix <sup>2</sup> patch panel VIK 48xE2000-S APC OS2 gray
1504807448-E	OpDAT fix <sup>2</sup> patch panel VIK 48xLC-D OS2 gray
1504807548-E	OpDAT fix <sup>2</sup> patch panel VIK 48xLC-D OM4 gray
1504807648-E	OpDAT fix <sup>2</sup> patch panel VIK 48xLC-D APC OS2 gray
1504807748-E	OpDAT fix <sup>2</sup> patch panel VIK 48xLC-D OM3 gray
1504807M48-E	OpDAT fix <sup>2</sup> patch panel VIK 48xLC-D OM5 gray
150480BA48-E	OpDAT fix <sup>2</sup> patch panel VIK 48xSC-D OM3 gray
150480BB48-E	OpDAT fix <sup>2</sup> patch panel VIK 48xSC-D OM4 gray
150480BM48-E	OpDAT fix <sup>2</sup> patch panel VIK 48xSC-D OM5 gray
150480E248-E	OpDAT fix <sup>2</sup> patch panel VIK 48xSC-D OS2 gray
150480F248-E	OpDAT fix <sup>2</sup> patch panel VIK 48xSC-D APC OS2 gray
1504857748-E	OpDAT fix <sup>2</sup> patch panel splice 48xLC-D OM3 gray
150485BA48-E	OpDAT fix <sup>2</sup> patch panel splice 48xSC-D OM3 gray
1504877548-E	OpDAT fix <sup>2</sup> patch panel splice 48xLC-D OM4 gray
150487BB48-E	OpDAT fix <sup>2</sup> patch panel splice 48xSC-D OM4 gray
150488BM48-E	OpDAT fix <sup>2</sup> patch panel splice 48xSC-D OM5 gray
1504895948-E	OpDAT fix <sup>2</sup> patch panel splice 48xE2000-S APC OS2 gray
1504897448-E	OpDAT fix <sup>2</sup> patch panel splice 48xLC-D OS2 gray
1504897648-E	OpDAT fix <sup>2</sup> patch panel splice 48xLC-D APC OS2 gray
150489E248-E	OpDAT fix <sup>2</sup> patch panel splice 48xSC-D OS2 gray
150489F248-E	OpDAT fix <sup>2</sup> patch panel splice 48xSC-D APC OS2 gray



Data sheet

Page 15/15

## OpDAT strain relief for M20

P/N

150240Z20Z-E

EAN 4251394679761

2025/07/11

Version: B

### Illustrations

Dimensional drawing

